## Nº 11040 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO	\		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB?			
WAS ATTACHED TO MAINSHOW BY DIAGRAM RELATION OF LATERAL TO WAR	NAME OF CONTRACTORL OF BUILDING SERVED.		
	No Inspection		
SIGNED	FILED AT ENGINEER'S OFFICE		
Inspector for City			

## Nº 11040

## OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

. )	- Λ	MASSILLO	N, OHIO,	4/7
Menon	RECEIVED OF	Jackha	let	FEE OF \$\sigma_2'
	FOR WHICH PERMISSION IS GRANTED.			
1/0/	TO TAP	SEWER ON TH	e	1. f-
	OF 12001111 5	AVE. ST. TYPE OF STRE	:ET	Salt
a) b)	THE PREMISES BEING LOT NO	15467	, HOUSE NO	2260
<b>3</b>	WORK TO BE DONE IN ACCORDANCE	WITH ORDINANCE NO. 19-1971	DULY PASSED BY THE	E CITY COUNCIL, AND
	OF THE DEPARTMENT OF PUBLIC SER	RVICE.		
	NAME OF CONTRACTOR	Plant		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.