## Nº 11059

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5./6-30	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 2480	THO MARKOLL SOM STREAM	
SIZE OF PIPE USED 6 17	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?	10-61	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
SIGNED BELO Samuel	1 0 5 5 10 0 5 5 5 10 0 5 5 5 5 5 5 5 5	
Inspector for City	FILED AT ENGINEER'S OFFICE	
•		

## Nº 11059

## OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

	MASSILLON, OHIO, 7464 /5
RECEIVED OF	S Franciscop FEE OF \$ 5
FOR WHICH PERMISSION IS GRANTED	Excavaling
TO TAPSE	WER ON THE
OF June 14 AVE. TY	PE OF STREET CONTROLE
THE PREMISES BEING LOT NO. 15473	, HOUSE NO
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO.	D. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
NAME OF CONTRACTOR	<u> </u>

Note: This permit covers work outside of building only. Any wor walls of building is subject to Massillon Board of Health Regulations.