Nº 11064

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-23-00	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO. //30	•		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB? 755	0 0.0.5		
WAS ATTACHED TO MAIN 745	NAME OF CONTRACTOR		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
	30' 30' 30'		
	30'		
	2 - This		
SIGNED Bir Caram	FILED AT ENGINEER'S OFFICE		
/Inspector for City	A STATE OF THE PARTY OF THE PAR		
REMARKS			

Nº 11064

OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

	, MASSILLON, OHIO	0,	
RECEIVED OF	-25 I_{\odot} I_{\odot}	FEE OF \$	
FOR WHICH PERMISSION IS GRANTED			
то тар	SEWER ON THE	<u>iddet</u>	
or			
THE PREMISES BEING LOT NO	<u>, э. у. / / ,</u> нос	USE NO	
WORK TO BE DONE IN ACCORDANCE WITH (ORDINANCE NO. 19-1971 DULY	PASSED BY THE CITY COUNCIL, AND	
OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR	<u>Like</u>		

Note: This permit covers work outside of building only. Any wor walls of building is subject to Massillon Board of Health Regulations.