Nº 11069

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-4-80	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM			
HOUSE NO. //55				
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH			
WAS LATERAL AT CURB? Yas	A			
WAS ATTACHED TO MAIN 725	NAME OF CONTRACTOR Johns Ede			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
	22° 8'DEEP [22° 8'DEEP			
SIGNED Rilland	, FILED AT ENGINEER'S OFFICE			
Inspector for City	THE OF THE PARTY O			
REMARKS				

Nº 11069

OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

•	MAS	SILLON, OHIO,/	lay 22
RECEIVED OF			FEE OF \$:
FOR WHICH PERMISSION IS GRANTED.	1/1/3	Executading	
TO TAP	SEWER (ON THE LANCE	- ^
OF COST STEERS	AVE.	F STREET 135/4/1	
THE PREMISES BEING LOT NO			
WORK TO BE DONE IN ACCORDANCE VOICE THE DEPARTMENT OF PUBLIC SER		-1971 DULY PASSED BY	THE CITY COUNCIL, AND
NAME OF CONTRACTOR	Las Come	liza	

Note: This permit covers work outside of building only. Any wor walls of building is subject to Massillon Board of Health Regulations.