

Nº 11072

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 5-30-00

IF SO, HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1460

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR Malcolm Egan

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Bill Parnas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11072

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
**PERMIT TO TAP SEWER**

MASSILLON, OHIO, \_\_\_\_\_

5/24, 20

RECEIVED OF \_\_\_\_\_

Malanite

FEE OF \$ \_\_\_\_\_

52

FOR WHICH PERMISSION IS GRANTED \_\_\_\_\_

REPAIR  
TO TAP  
CUTOFF

Sanitary

SEWER ON THE \_\_\_\_\_

S

OF \_\_\_\_\_

Gibson Ave

AVE.

ST. TYPE OF STREET \_\_\_\_\_

Asphalt

THE PREMISES BEING LOT NO. \_\_\_\_\_

14

HOUSE NO. \_\_\_\_\_

1460

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE  
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR \_\_\_\_\_

MOS

**Note: This permit covers work outside of building only. Any work inside  
walls of building is subject to Massillon Board of Health regulations.**