

Nº 11073

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 5-24-00

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 335

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Joseph M. King
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N^o 11073

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/24

RECEIVED OF Lisat

FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP
CUTOFF

SEWER ON THE West SI

OF Stanhope Ave.

ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. _____

, HOUSE NO. 335

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Lisat

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.