

Nº 11080

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED _____ IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____

SIZE OF PIPE USED _____ DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____ NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

No Inspection

SIGNED *B. J. P. [Signature]* FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS _____

Nº 11080

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, June 12, 20

RECEIVED OF _____ FEE OF \$ _____

FOR WHICH PERMISSION IS GRANTED Fish Wrecking

REPAIR
TO TAP Sanitary SEWER ON THE North S
CUTOFF

OF Lincoln Way East AVE asphalt
ST TYPE OF STREET

THE PREMISES BEING LOT NO. Massillon Village Center - Gabriel Brothers HOUSE NO. 2406 Lincoln

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Estech Wheeling

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.