## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4.29.60	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED 4 11	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 325	
WAS ATTACHED TO MAIN 45 S	NAME OF CONTRACTOR 26 50.
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
	1 15 5 DEE! 17 220 12. 0 1 25 P
SIGNED Bill Carrier Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

Nº 11085

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

RECEIVED OF	MASSILLON, OHIO,
FOR WHICH PERMISSION IS GRANTED	
	EWER ON THE
OF X A A A A A A STATE STATE	TYPE OF STREET MENALL
	-8 9 , HOUSE NO. / 1705
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO.	, , , , , , , , , , , , , , , , , , ,
	. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.	•
NAME OF CONTRACTOR	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.