

Nº 11087

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-13-00

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 2861

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR Hole.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

LAN



SIGNED

B. J. P.

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11087

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, July 10, 20

RECEIVED OF H+W Contractors FEE OF \$

FOR WHICH PERMISSION IS GRANTED H-W

REPAIR TO TAP Sanitary SEWER ON THE South S
CUTOFF

OF Lawton Circle NW AVE. ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 15946, HOUSE NO. 2861

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR H-W Contractors

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.