


Nº 11089

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-15-00 IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____
HOUSE NO. 1950
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? YES
WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR Malaviti Egn.
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Bill Rogers Inspector for City FILED AT ENGINEER'S OFFICE _____
45°+22° 10'085P

REMARKS _____

Nº 11089

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, _____

7/10/20

RECEIVED OF _____

Malanite

FEE OF \$ _____

57

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP
CUTOFF

Sanitary

SEWER ON THE _____

East

S

OF _____

Carl Winter St

AVE.

ST. TYPE OF STREET _____

Asphalt

THE PREMISES BEING LOT NO. _____

15996

, HOUSE NO. _____

1950

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

Homes by Ashley

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.