N° $1\overline{1092}$

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 7-18-00 | IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM |
|---|--|
| SIZE OF PIPE USED 6 17 WAS LATERAL AT CURB? | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH (1) C / |
| WAS ATTACHED TO MAIN | NAME OF CONTRACTOR Johns Che |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU | IILDING SERVED. |
| J. | 9 10 5 F |
| SIGNED BLU Conset | FILED AT ENGINEER'S OFFICE |
| REMARKS | · |

Nº 11092

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

| MASSILLON, OHIO, 7/7/20_ RECEIVED OF MASSILLON, OHIO, FEE OF \$ 5 |
|--|
| FOR WHICH PERMISSION IS GRANTED |
| SEWER ON THE ACTUAL OF STREET ACTUAL OF STREET |
| THE PREMISES BEING LOT NO |
| VORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE. |
| IAME OF CONTRACTOR |

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.