## Nº 11095

REMARKS \_\_\_\_\_

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

HOUSE NO. 221.5  SIZE OF PIPE USED 6  WAS LATERAL AT CURB? Y I S  WAS ATTACHED TO MAIN 4.5	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH  NAME OF CONTRACTOR  PORTON  STREAM  NAME OF CONTRACTOR  PORTON  STREAM  NAME OF CONTRACTOR  PORTON  STREAM  S	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	7' PREP 77'	
SIGNED / Inspector for City	Cy Off P   FILED AT ENGINEER'S OFFICE	

Nº 11095 c/c#21411

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

<b></b>		
	MASSILLON, OHIO,	// <u>// 20</u>
RECEIVED OF _	Dorthagly	FEE OF \$
OR WHICH PERMISSIO	IN IS GRANTED	
REPAIR O TAP	SEWER ON THE	m block
of <del>Arios</del>	AVEC. ST. TYPE-OF STREET	An Hode 14
HE PREMISES BEING L	OT NO, HOUSE NO.	o
		•
ORK TO BE DONE IN A	ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE	ECITY COUNCIL, AND RULES OF THE
EPARTMENT OF PUBLI	IC SERVICE.	in the state of t
AME OF CONTRACTOR	- Seffellest Houses	- 1/ 

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.