## $N^{0}$ 11100

REMARKS \_\_\_\_\_

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7/25/00 HOUSE NO. 260	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	24'
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
was lateral at curb?	NAME OF CONTRACTOR	Tisset
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF E	BUILDING SERVED.	260 Starbrook 8.5' ped 18.6'
// //		-38' L" 24" -31' 6"
SIGNED Inspector for City	FILED AT ENGINEE	R'S OFFICE 8"

Nº 11100

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

RECEIVED OF	MASSILLON, C	OHIO,FEE OF	$\frac{7}{\sqrt{3}}\sqrt{\frac{20}{20}}$
FOR WHICH PERMISSION IS GRANTED			
TO TAP CUTOFF.	SEWER ON THE AYE. ST. TYPE OF STREET	1 4 4 4 d	
THE PREMISES BEING LOT NO		HOUSE NO.	(61)
WORK TO BE DONE IN ACCORDANCE WITH ORI DEPARTMENT OF PUBLIC SERVICE.	DINANCE NO. 19.1971 DULY PASS	ED BY THE CITY COUNCIL, AND	) RULES OF THE

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.