N^{0} $1\overline{1}\overline{1}0\overline{5}$

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-7-60	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM			
HOUSE NO. 3.56	THO MANIOLE DOWN OFFICAN			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT			
WAS LATERAL AT CURB?	CURB LINE AND DEPTH			
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Jeruin Ele-			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
	10 ABS LIDES NA 4'-450			
SIGNED BILL CONTROL OF CITY	FILED AT ENGINEER'S OFFICE			
REMARKS				

Nº 11105

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON,	ОНЮ,	August, 207	
RECEIVED OF		F	FEE OF \$	
FOR WHICH PERMISSION IS GRANTED	Jelly 5	Exeminting		
REPAIR TO TAP SALEY Y	SEWER ON THE			
OF Show Aut	AVE.	a>/a	hell	
THE PREMISES BEING LOT NO.	15885	., HOUSE NO	356	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.				
NAME OF CONTRACTOR	Y'S Exempling			

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.