N^{o} 11111

REMARKS _____

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED \$47.00 HOUSE NO. 2230 SIZE OF PIPE USED 67 WAS LATERAL AT CURB? 455	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Mahariter Eles
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BL	JILDING SERVED.
	100 DEEP
	10 5 22
SIGNED Bill Inspector for City	FILED AT ENGINEER'S OFFICE
••	

N^{0} 11111

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

ſ	MASSILLON, (оню,	8/14	/ //, 20
RECEIVED OF Malamit	<u>.</u>	·····	FEE OF \$	<u>37.0</u>
FOR WHICH PERMISSION IS GRANTED		***************************************		
TO TAP SINTING SEWE	R ON THE	lax	Ć.	
CUTOFF AVE.	OF STREET	and	latt	
THE PREMISES BEING LOT NO. 11792		, HOUSE NO.	<u> </u>	
<u> </u>				•
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1	971 DULY PASS	SED BY THE CITY COL	INCIL, AND RUI	ES OF THE
DEPARTMENT OF PUBLIC SERVICE.	_			
NAME OF CONTRACTOR Malautt				

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.