		-		
Nº 1	1	1	1	6

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO, HOW AND LOCATION FROM
HOUSE NO.	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF	BUILDING SERVED.
No Inspection	
SIGNEDInspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

Nº 11116

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	710	MASSILLON,	DHIO,	<u> </u>
RECEIVED OF	- / - / - }			FEE OF \$
FOR WHICH PERMISSION IS GRANTED				
REPAIR TO TAP CUTOFF	SEWE	R ON THE	J. W. A.	A. J. M.
OF AND TEAR.			<u>As</u>	at the state of
THE PREMISES BEING LOT NO.	/(-0/0)	ALONG THE RESIDENCE OF THE PROPERTY OF THE PRO	, HOUSE NO	- 4150
WORK TO BE DONE IN ACCORDANCE WIT	TH ORDINANCE NO. 19.	1971 DULY PASS	GED BY THE CITY CO	JNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.	1 200		•	
NAME OF CONTRACTOR	7\$\\			

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.