

N<sup>o</sup> 11123

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-31-00 IF SO, HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM \_\_\_\_\_


HOUSE NO. 2323

SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH \_\_\_\_\_

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes NAME OF CONTRACTOR Malmuth Etc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Bill P. FILED AT ENGINEER'S OFFICE \_\_\_\_\_

Inspector for City

REMARKS \_\_\_\_\_

Nº 11123

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

# PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/28 80

RECEIVED OF Malamite FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED \_\_\_\_\_

REPAIR TO TAP Sanitary SEWER ON THE West S  
CUTOFF \_\_\_\_\_

OF Amherwood AVE. ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 14727, HOUSE NO. 2323

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Malamite

**Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.**

20' water m/h  
40' in 1/6