


N<sup>o</sup> 11131

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 9-12-00 IF SO, HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM \_\_\_\_\_  
HOUSE NO. 1845  
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH \_\_\_\_\_  
WAS LATERAL AT CURB? Yes  
WAS ATTACHED TO MAIN Yes NAME OF CONTRACTOR Maintenance Corp.  
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED B. B. B. FILED AT ENGINEER'S OFFICE \_\_\_\_\_

Inspector for City

REMARKS \_\_\_\_\_

N<sup>o</sup> 11131

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

# PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/11, 20  

RECEIVED OF Malumite FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED   

REPAIR TO TAP Sanitary SEWER ON THE West SIDE OF    CUTOFF

OF John Crockett St AVE. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 15989, HOUSE NO. 1845

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Malumite

**Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.**