$N^{\underline{0}}$ $1\overline{1}13\overline{2}$

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9.11.00	IF SO, HOW AND LOCATION FROM Doe's Tuto MI
HOUSE NO. 722-724	·
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	A ()
WAS ATTACHED TO MAIN 48 5	NAME OF CONTRACTOR Holderburn Lecure
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
	10' 3'ORE NA 10' SET DEOP
SIGNED	FILED AT ENGINEER'S ÓFFICE
REMARKS	

Nº 11132

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	RECEIVED OF All Gum FEE OF \$ 2
	FOR WHICH PERMISSION IS GRANTED
	THE PREMISES BEING LOT NO. TO TAP CUTOFF OF JULY LIVETURE WER ON THE MULT AVE THE PREMISES BEING LOT NO. (7) HOUSE NO. 7) 7) 7) HOUSE NO.
4	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE. NAME OF CONTRACTOR

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.