

Nº 11134

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 9-25-00

IF SO, HOW AND LOCATION FROM

HOUSE NO. 1225

FIRST MANHOLE DOWN STREAM

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE

WAS LATERAL AT CURB? Yes


DOWN STREAM TO DITCH AT

CURB LINE AND DEPTH

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

B. P.

Inspector, for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11134

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, _____

9/13/20

RECEIVED OF _____

Bontingen

FEE OF \$ _____

50

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP
CUTOFF

Sanitary

SEWER ON THE _____

West

S

OF _____

Londale St

AVE.

ST TYPE OF STREET _____

Asphalt

THE PREMISES BEING LOT NO. _____

16123

HOUSE NO. _____

1225

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

Efficient Homes

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.