


N^o 11142

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-10-00 IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 74'
HOUSE NO. 1155
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? YES
WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR Malawati Epc.
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED B. L. P. Inspector for City FILED AT ENGINEER'S OFFICE

REMARKS LINE IS VERY FLAT LITTLE FALL

Nº 11142

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, _____

9/15/20

RECEIVED OF

Malawite

FEE OF \$

50

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP
CUTOFF

Wentworth

SEWER ON THE

West

SI

OF

Waller Rd

AVE.

ST TYPE OF STREET

duplex

THE PREMISES BEING LOT NO.

16038

, HOUSE NO.

1157

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Malawite

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**