

N^o 11143

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 9-19-00

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

200'

HOUSE NO. 235

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Tissot

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

J. H. in Hig

Inspector for City

FILED AT ENGINEER'S OFFICE

200'
8"

REMARKS

Nº 11143

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/18, 2000

el RECEIVED OF Lisat

FEE OF \$

52

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP
CUTOFF

Sanitary SEWER ON THE West S

OF 29th St NW

AVE.

ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 15129

, HOUSE NO. 235

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Lisat

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**