Nº 11151

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED /0-3-00 HOUSE NO. 425 SIZE OF PIPE USED 6"	IF SO, HOW AND LOCATION FIRST MANHOLE DOWN STI DISTANCE FROM FIRST MAI DOWN STREAM TO DITCH A CURB LINE AND DEPTH	NHOLE	
WAS LATERAL AT CURB? Yes		Rouglaman	
WAS ATTACHED TO MAINYES	NAME OF CONTRACTOR	D00 300 0000000000000000000000000000000	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF B	UILDING SERVED:	425 29th St	Z_{\Rightarrow}
		6.5°dp@hause	
		66 [,]	
		 -11.5*dp	
. // . // .		8'stackEmain	158′
SIGNED WI W	FILED AT	ENGINEER'S OFFICE	8′
Inspector for City			
DEMARKS			

Nº 11151

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

//	MASSILLON, OHIO,	/ <i>C</i> / \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
RECEIVED OF	und	FEE OF \$
FOR WHICH PERMISSION IS GRANTED		
	ER ON THE	dert
OF 14 M AVE. ST. TYPI	E OF STREET	oud art
THE PREMISES BEING LOT NO.	, HOUSE NO	9 421-
,, , , , , , , , , , , , , , , , ,	···	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.	1971 DULY PASSED BY THE CITY (COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.	4	•
NAME OF CONTRACTOR	and	
. (\	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.