N^{0} $1\overline{1}\overline{1}\overline{5}\overline{2}$

REMARKS _____

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	10/5/00	IF SO, HOW AND LOCATION FROM	170′	
HOUSE NO.	2935	FIRST MANHOLE DOWN STREAM		
SIZE OF PIPE USED	6*	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT	•	
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH		
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR	Boughman	
SHOW BY DIAGRAM RELATION O	OF LATERAL TO WALL OF	BUILDING SERVED.	18' 2935 Gordon	
a Ala	i Idon		12.75'— 7'5'dpēhause 45° 45° 12'— 10'dp 34'— 11'stackēnain. 170'	
SIGNED	Inspecto for City	FILED AT ENGINEER'S	S OFFICE	

Nº 11152

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON,	ОНЮ,	<u> </u>	
RECEIVED OF BOUGHM	aA		FEE OF \$	
FOR WHICH PERMISSION IS GRANTED				
REPAIR TO TAP	SEWER ON THE		south	
001011	AVE.		neobalt	
of <u>(=,c///////</u>	SI. TYPE OF STREET		7777777	
THE PREMISES BEING LOT NO.		_, HOUSE NO	<u> 2935 </u>	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE	: NO. 19.1971 DULY PAS	SED BY THE CIT	Y COUNCIL, AND RULES OF TH	E
DEPARTMENT OF PUBLIC SERVICE.				
NAME OF CONTRACTOR	an Excaver	ting	· · · · · ·	-

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.