

Nº 11155

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-6-00

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1835

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Malouin Co.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Bill P.
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11155

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, _____

10 / 04
20

RECEIVED OF _____

FEE OF \$ _____

FOR WHICH PERMISSION IS GRANTED _____

Malavite

REPAIR
TO TAP
CUTOFF

tap sanitary

SEWER ON THE _____

north

SI

OF _____

Case Westria Drive

AVE.
ST. TYPE OF STREET

asphalt

THE PREMISES BEING LOT NO. _____

15971

, HOUSE NO. _____

1835

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

Malavite

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**