

N^o 11157

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED _____ IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____ DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

SIZE OF PIPE USED _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____ NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SIGNED _____ FILED AT ENGINEER'S OFFICE _____

Inspector for City

REMARKS _____

Nº 11157

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/06/20

RECEIVED OF _____ FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED Frank's Excavating

REPAIR TO TAP tap sanitary SEWER ON THE South S
CUTOFF

OF Forest Ave SE AVE. ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 11290-11291-11292 HOUSE NO. 1605

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

9 NAME OF CONTRACTOR Frank's Excavating

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.