

Nº 11168

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-26-00

IF SO, HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

HOUSE NO. 2560

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR First Corp.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED B. P.  
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11168

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
**PERMIT TO TAP SEWER**

MASSILLON, OHIO, \_\_\_\_\_, 20 \_\_\_\_\_

RECEIVED OF \_\_\_\_\_ FEE OF \$ \_\_\_\_\_

FOR WHICH PERMISSION IS GRANTED Tissot Excavating

REPAIR  
TO TAP tap sanitary SEWER ON THE lot S  
CUTOFF

OF Angus Ave SE AVE.  
ST. TYPE OF STREET private

THE PREMISES BEING LOT NO. 15475, HOUSE NO. 2560

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE  
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Tissot

**Note: This permit covers work outside of building only. Any work inside  
walls of building is subject to Massillon Board of Health regulations.**