

Nº 11177

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 11/14/00

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

172'

HOUSE NO. 350

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Tissot

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Jelly in King

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11177

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/13, 2011

RECEIVED OF Insent FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP Sanitary SEWER ON THE East SIDE
CUTOFF _____

OF Hubbrook Ave. AVE.
STATE OF STREET Asphalt

THE PREMISES BEING LOT NO. 15143, HOUSE NO. 350

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Insent

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**