Nº 11190

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 12,19,00 HOUSE NO. 32	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
SIZE OF PIPE USED 6 11	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB? 49 9	310 614		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR // Lunghage City		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
PIX	5'DEEP 450		
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE		
DEMADICS			

Nº 11190

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO,	12/22/260
RECEIVED OF		FEE OF \$
FOR WHICH PERMISSION IS GRANTED	Murphy Enterpris	SP 5
REPAIR TO TAP	, SEWER ON THE	Tall.
of Medfeldine it it Se		
THE PREMISES BEING LOT NO	/ <u>/ 76 /</u> , HOUSE NO.	32
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCI DEPARTMENT OF PUBLIC SERVICE.	E NO. 19.1971 DULY PASSED BY THE C	CITY COUNCIL, AND RULES OF THE
NAME OF CONTRACTOR	L F. Hisprises	_

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.