

Nº 11191

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED _____ IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____

SIZE OF PIPE USED _____ DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____ NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

5416
495-

SIGNED _____ FILED AT ENGINEER'S OFFICE _____

Inspector for City

REMARKS _____

N^o 11191

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 12/27/00, 20

RECEIVED OF Efficient Homes FEE OF \$ 50.

FOR WHICH PERMISSION IS GRANTED Bontager Excavating

REPAIR TO TAP for repair SEWER ON THE South SIDE

CUTOFF OF Cassworth Ave. N. AVE. ST. TYPE OF STREET residential

THE PREMISES BEING LOT NO. 15463, HOUSE NO. 1075

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Bontager

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.