

Nº 11193

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 1-17-01 IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____


HOUSE NO. 2847

SIZE OF PIPE USED 16" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR W. H. Stone Etc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Bio Pappas FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS _____

Nº 11193

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/5, 20

RECEIVED OF William Stone FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED

REPAIR TO TAP SEWER ON THE S
CUTOFF AVE.

OF ST. TYPE OF STREET

THE PREMISES BEING LOT NO. 1314, HOUSE NO. 2817

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR William Stone

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.