## Nº 11195

REMARKS \_\_\_\_

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	1/24/01	IF SO, HOW AND LOCATION FROM	66′
HOUSE NO.	315	FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED	6 <b>″</b>	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?	yes		
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR	Exit C&D
SHOW BY DIAGRAM RELATION O	OF LATERAL TO WALL OF 6	cut off for 315 3rd st lateral is 66' w of mh 6' n of fence 8'dp	and at the state of the state o

## Nº 11195

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

RECEIVED OF	MASSILLON,	ОНЮ,	FEE OF \$	د. 20
FOR WHICH PERMISSION IS GRANTED _				
REPAIR TO TAP	SEWER ON THE		Mext	
OF	AVE.	·	12 1 1 1 to t	
THE PREMISES BEING LOT NO	9249	_, HOUSE NO	3/5	
WORK TO BE DONE IN ACCORDANCE WIT DEPARTMENT OF PUBLIC SERVICE.	TH ORDINANCE NO. 19.1971 DULY PAS	SED BY THE CITY	COUNCIL, AND RULES OF T	ΉE
NAME OF CONTRACTOR	Zart ( ) D		-	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.