

N^o 11196

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 1/24/01 IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM Lateral cut-off @ MH
HOUSE NO. 323
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? _____
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Exit C & D
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SIGNED _____

J. M. King
Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11196

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 1/9/20

RECEIVED OF Encl C/D FEE OF \$ 11

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP _____ SEWER ON THE _____ SI
CUTOFF _____
OF _____ AVE.
ST. TYPE OF STREET _____

THE PREMISES BEING LOT NO. 4248, HOUSE NO. 323

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Encl C/D

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**