


Nº 11200

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 1/10/01 IF SO, HOW AND LOCATION FROM 191'
FIRST MANHOLE DOWN STREAM
HOUSE NO. 1500
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Malavite

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED [Signature] Inspector for City FILED AT ENGINEER'S OFFICE _____

REMARKS _____

No 11200

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/10/20

RECEIVED OF

Malante

FEE OF \$

50

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP
CUTOFF

Sandberg

SEWER ON THE

North

S

OF

Gibson St

AVE.

ST. TYPE OF STREET

asphalt

THE PREMISES BEING LOT NO.

15600

HOUSE NO.

1500

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Malante

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.

11/10/01

MDS

on SE

update

on

300

to

Malante

000

n