

N^o 11201

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 1-11-01

IF SO, HOW AND LOCATION FROM

HOUSE NO. 2340

FIRST MANHOLE DOWN STREAM

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE

DOWN STREAM TO DITCH AT


WAS LATERAL AT CURB? YES

CURB LINE AND DEPTH

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Bio Pappas
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11201

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/10 2020

RECEIVED OF John's Excavating

FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP
CUTOFF

SEWER ON THE East

OF Augusta St

AVE.

ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 154129

HOUSE NO. 2340

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR John's Exc

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.