


Nº 11202

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 1-11-01 IF SO, HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM \_\_\_\_\_  
HOUSE NO. 1830  
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH \_\_\_\_\_  
WAS LATERAL AT CURB? YES  
WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR M. L. L. L. L.  
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED B. W. P. P.  
Inspector for City

FILED AT ENGINEER'S OFFICE \_\_\_\_\_

REMARKS \_\_\_\_\_

Inspect 11/11 am.

Nº 11202

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/10/20

RECEIVED OF Malonte FEE OF \$ 50

16 FOR WHICH PERMISSION IS GRANTED

REPAIR TO TAP CUTOFF Sanitary SEWER ON THE East S

OF Case Western AVE ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 15991, HOUSE NO. 1830

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Malonte

**Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.**