

Nº 11216

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3-7-01

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

65'

HOUSE NO. 2535

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? Y/E 3

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

Tissot Etc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

B. J. [Signature]
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N^o 11216

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, _____

2/28

RECEIVED OF _____

Grant

FEE OF \$ _____

52

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP
CUTOFF

Sanitary

SEWER ON THE _____

South

S

OF _____

William B. 7th

AVE.

ST TYPE OF STREET _____

asphalt

THE PREMISES BEING LOT NO. _____

14856

, HOUSE NO. _____

2535

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

Grant

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**