


Nº 11218

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 3-7-01 IF SO, HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM \_\_\_\_\_  
HOUSE NO. 2345  
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH \_\_\_\_\_  
WAS LATERAL AT CURB? YES  
WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR Malanti Etc.  
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Bio P. Agius  
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N<sup>o</sup> 11218

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
**PERMIT TO TAP SEWER**

MASSILLON, OHIO, March 5, 20  

RECEIVED OF Malvite Excavating FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED Malvite

REPAIR  
TO TAP tap sanitary SEWER ON THE AS South S  
CUTOFF

OF Amberwood Circle AVE. SE TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 11724, HOUSE NO. 2345

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE  
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Malvite

**Note: This permit covers work outside of building only. Any work inside  
walls of building is subject to Massillon Board of Health regulations.**