


Nº 11220

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 3-15-01 IF SO, HOW AND LOCATION FROM 43'  
FIRST MANHOLE DOWN STREAM  
HOUSE NO. 1540  
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH  
WAS LATERAL AT CURB? YES  
WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR Malone's Etc.  
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Bill Pappas  
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11220

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
**PERMIT TO TAP SEWER**

MASSILLON, OHIO, 3/14, 2020

RECEIVED OF Malawite

FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED \_\_\_\_\_

REPAIR  
TO TAP  
CUTOFF

SEWER ON THE North S

OF Gibson St

AVE.

ST. TYPE OF STREET Highway

THE PREMISES BEING LOT NO. 15602

, HOUSE NO. 1540

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE  
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR MA DS

**Note: This permit covers work outside of building only. Any work inside  
walls of building is subject to Massillon Board of Health regulations.**