

Nº 11221

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 2-30-01

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

GOES INTO RH

HOUSE NO. _____

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR Pachon Epc

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Bill Pappas
Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11221

Dwayne ,
OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/15/01, 2001

RECEIVED OF _____ FEE OF \$ 11

FOR WHICH PERMISSION IS GRANTED Pachan Construction

REPAIR TO TAP tap sanitary SEWER ON THE west S
CUTOFF

OF 27th St NE AVE. ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. Out lot 330, HOUSE NO. Kmarl East

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Pachan Construction

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.