

Nº 11223

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3-26-01

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

238'

HOUSE NO. 2489

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR Malanista Etc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____

Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11223

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/23/01, 2001

RECEIVED OF _____ FEE OF \$ _____

FOR WHICH PERMISSION IS GRANTED Malavite Excavation

TO REPAIR TAP CUTOFF top sanitary SEWER ON THE South SIDE

OF Malone Ave SE AVE. ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 16076, HOUSE NO. 2489

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Malavite

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.