## Nº 11231

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	3/30/01	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 137'	197/	
HOUSE NO.	213		13/	
SIZE OF PIPE USED	6*	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB?	yes			
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR	Exit C&D	
SHOW BY DIAGRAM RELATION O	OF LATERAL TO WALL OF B			
	North ne	cut-off for 213 2nd St NE	steral cut-off 29' Behind curb.	
	Θ—	137' Fron nh & intersection of 2nd & Nor	-th	Z
ı	,	2nd st	ne	
SIGNED JOHN	Inspector for City	FILED AT ENGINEER'S (	OFFICE	
, , 0	mapedial for only			
REMARKS				

Cut, of

## $N^{\underline{0}}$ 11231

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO,	3/29,20_
RECEIVED OF	FEE OF \$
FOR WHICH PERMISSION IS GRANTED	
REPAIR TO TAP X autasswert on the	I am billet
CUTOFF)  AVE  SPRING OF STREET	
THE PREMISES BEING LOT NO, HOUSE	/: 40 / 3
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY T	THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.	en de la companya de La companya de la co
NAME OF CONTRACTOR	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.