


N^o 11234

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4/5/01 IF SO, HOW AND LOCATION FROM 121'
FIRST MANHOLE DOWN STREAM
HOUSE NO. 2995
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Holderbaum

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED [Signature] INSPECTOR FOR CITY FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11234

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/3, 20

RECEIVED OF Asa Holderbaum FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP SEWER ON THE West SIDE
CUTOFF

OF Stanton St AVE. TYPE OF STREET Asphalt

THE PREMISES BEING LOT NO. 15789, HOUSE NO. 2995

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Asa Holderbaum

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.