

Nº 11241

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-10-01 IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____


HOUSE NO. 2500

SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR Bontroyer

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED B. J. P. Jones FILED AT ENGINEER'S OFFICE _____

Inspector for City

REMARKS _____

N^o 11241

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/1, 20

RECEIVED OF Bonttrager Exploring FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED Effluent Hook

REPAIR TO TAP Sanitary SEWER ON THE North S
CUTOFF

OF Maplewood AVE. ST. TYPE OF STREET Asphalt

THE PREMISES BEING LOT NO. 16090, HOUSE NO. 2170

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Bonttrager - Ch 11-15-66

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.