


N^o 11245

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-17-01 IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____
HOUSE NO. 2830
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? Yes
WAS ATTACHED TO MAIN Yes NAME OF CONTRACTOR Malamitie Etc.
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED R. P. [Signature] FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS _____

Nº 11245

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/11/01, 20

RECEIVED OF Malavite FEE OF \$ 5.

FOR WHICH PERMISSION IS GRANTED Malavite

REPAIR TO TAP tap sanitary SEWER ON THE north S
CUTOFF

OF Turning Leaf Ave AVE. ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 15941, HOUSE NO. 2830

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Malavite

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.