		•			
Nº	1	1	2	4	ϵ

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

HOUSE NO SIZE OF PIPE USED WAS LATERAL AT CURB?	FIRST MANHOLE DOWN STREAM DISTANCE FROM FIRST MANHOLE
WAS ATTACHED TO MAIN SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BE NO Inspection	NAME OF CONTRACTOR
SIGNEDInspector for City	FILED AT ENGINEER'S OFFICE

Nº 11246

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO,
RECEIVED OF Cottrill	FEE OF S
FOR WHICH PERMISSION IS GRANTED	
REPAIR TO TAP SEWE	en on the west
CUTOFF	
OF Cliff N W ST. TYPE	FOF STREET ASPN-14
THE PREMISES BEING LOT NO. 2508	, HOUSE NO661
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19:	1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR COTTY \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.