


N<sup>o</sup> 11249

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-19-01 IF SO, HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM \_\_\_\_\_  
HOUSE NO. 1040  
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH \_\_\_\_\_  
WAS LATERAL AT CURB? YES  
WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR S. M. HERR  
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED B. H. P. FILED AT ENGINEER'S OFFICE \_\_\_\_\_  
Inspector for City

REMARKS \_\_\_\_\_

Nº 11249

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
**PERMIT TO TAP SEWER**

MASSILLON, OHIO, 4/18/01, 20

RECEIVED OF Steve Miller FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED Steve Miller Excavating

REPAIR TO TAP tap sanitary SEWER ON THE East S  
CUTOFF

OF Lonedale Street NW AVE. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 10-017, HOUSE NO. 10410

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Miller Excavating

**Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.**