

Nº 11257

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-26-01

IF SO, HOW AND LOCATION FROM

FIRST MANHOLE DOWN STREAM

HOUSE NO. 2311

DISTANCE FROM FIRST MANHOLE

SIZE OF PIPE USED 6"

DOWN STREAM TO DITCH AT


WAS LATERAL AT CURB? Yes

CURB LINE AND DEPTH

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

B. W. P.
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11257

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/6/20

RECEIVED OF *McLennan* FEE OF \$ *50*

FOR WHICH PERMISSION IS GRANTED

REPAIR TO TAP *Sanitary* SEWER ON THE *South* SIDE
CUTOFF

OF *McLennan Ave.* AVE. ST. TYPE OF STREET *Highway*

THE PREMISES BEING LOT NO. *15960*, HOUSE NO. *2311*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Logan Taylor*

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.