Nº 11258

REMARKS _____

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-30-5/	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
WAS LATERAL AT CURB?	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH NAME OF CONTRACTOR A A A A A A A A A A A A A A A A A A A
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU	JILDING SERVED.
	28' -450 9/2000
SIGNED Bill Green	FILED AT ENGINEER'S OFFICE
Inspector for City	

Nº 11258

OFFICE OF THE DIRECTOR OF PUBLIC SERVICI

PERMIT TO TAP SEWER
MASSILLON, OHIO,
RECEIVED OF FEE OF \$ FEE OF \$
REPAIR TAP
E PREMISES BEING LOT NO. 101/5 HOUSE NO. 101/5
ORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
ME OF CONTRACTOR

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.