

Nº 11265

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED _____ IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____

SIZE OF PIPE USED _____ DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____ NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

No Inspection

SIGNED _____ FILED AT ENGINEER'S OFFICE _____

Inspector for City

REMARKS _____

Nº 11265

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, _____

5/4/20

RECEIVED OF _____

FEE OF \$ _____

50

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP
CUTOFF

SEWER ON THE _____

S

OF _____

AVE.

ST. TYPE OF STREET _____

THE PREMISES BEING LOT NO. _____

11313

, HOUSE NO. _____

2459

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

U. Chausse

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.